

# SVHC BIZTONSÁGOS HASZNÁLATI ÚTMUTATÓ

## A REACH KÜLÖNÖS AGGODALOMRA OKOT ADÓ (SVHC) ANYAGOKRÓL SZÓLÓ 33. SZÁMÚ CIKKE

Kedves Ügyfelünk!

A REACH rendelet (EK 1907/2006) 33(1) cikkelyének célja, hogy a szállított termékek vásárlói lehetőséget kapjanak azoknak a szükséges kockázatkezelési intézkedések a megtételére, amelyek az engedélyezendő anyagok legfrissebb listáján szereplő, különös aggodalomra okot adó (SVHC) anyagoknak az árucikkben való jelenlétéből fakadhatnak, garantálva ezzel azok biztonságos felhasználását.

A FORD támogatja általánosságban a REACH és konkrétan a 33(1) cikkely mögöttes célkitűzéseit, amelyek összhangban állnak termékeink felelősségteljes előállítására, kezelésére és felhasználására vonatkozó saját kötelezettségvállalásunkkal.

### **Az SVHC anyagok azonosítása**

A részegységekben 0,1 tömegszázalék (w/w) feletti arányban jelen lévő SVHC anyagok az ellátási láncunkból származó tájékoztatáson és saját termékadatainkon alapuló legjobb tudásunk szerint megegyeznek a konkrét járművekre/alkatrészekre vonatkozó SVHC-listáinkban felsoroltakkal.

### **Az SVHC anyagokat tartalmazó árucikkek biztonságos felhasználására vonatkozó specifikus adatok**

Az SVHC anyagokat tartalmazó árucikkek biztonságos felhasználására vonatkozó esetleg szükséges specifikus adatokat a konkrét járművekre/alkatrészekre vonatkozó SVHC-listáink tartalmazzák.

### **Az egyes árucikkek biztonságos felhasználására vonatkozó általános adatok**

Minden FORD járműhöz tartozik kezelési útmutató, amely tartalmazza a jármű tulajdonosának, illetve üzemben tartójának szóló, a biztonságos felhasználásra vonatkozó adatokat. Emellett a szervizszemélyzet számára a FORD járművek és gyári alkatrészek javításáról és szervizeléséről szóló tájékoztatója is tartalmaz biztonságos felhasználásra vonatkozó információkat.

A jármű alkatrészeiben esetleg jelenlévő, az illető járműre/alkatrészre vonatkozó SVHC-listán feltüntetett SVHC anyagokat olyan módon alkalmaztuk, hogy a felhasználókra minimális hatást gyakorolhassanak, az emberekre és a környezetre általuk jelentett veszély pedig kizárható legyen, amennyiben a járművet és alkatrészeit rendeltetésszerűen használják, továbbá az esetleges javításokat, szervizeléseket és karbantartásokat a rájuk vonatkozó műszaki utasítások betartásával és az iparágban bevált gyakorlat szerint végzik el.

Az élettartamuk végét elérő járművek az Európai Unióban csak erre jogosult hulladékkezelő (ATF) létesítményben helyezhetők el legálisan. A járműalkatrészeket a helyileg hatályos törvények és hatósági előírások betartásával kell hulladéklerakóba helyezni.

## Modell: Ford Focus

Az SVHC-lista az Európai Vegyianyag-ügynökség (ECHA) által vezetett, 2026. január 1-jén érvényes jelöltlistán alapul

Az SVHC anyagokat tartalmazó árucikkek biztonságos felhasználására vonatkozó specifikus adatok

Nem szükséges külön felhasználási tájékoztatás – ezeknél a cikkeknél a biztonságos felhasználásra vonatkozó általános adatokat kell figyelembe venni.

| Commodity                     | REACH SVHCs                                                             |
|-------------------------------|-------------------------------------------------------------------------|
| Accessories                   | Lead [7439-92-1]                                                        |
|                               | Octamethylcyclotetrasiloxane [556-67-2]                                 |
| Air Induction                 | Bumetrizole [3896-11-5]                                                 |
|                               | Lead [7439-92-1]                                                        |
| Auto Transmission             | Lead [7439-92-1]                                                        |
| Auto Transmission Shifter     | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
|                               | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]   |
|                               | C,C'-azodi(formamide) [123-77-3]                                        |
|                               | Lead [7439-92-1]                                                        |
| Body and Security Electronics | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
|                               | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]   |
|                               | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
|                               | Lead [7439-92-1]                                                        |
| Body Covers and Ornamentation | Lead [7439-92-1]                                                        |
| Body Moldings - Roof Rack     | C,C'-azodi(formamide) [123-77-3]                                        |
| Brakes                        | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
|                               | Lead [7439-92-1]                                                        |
| Bumpers and Spoilers          | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
|                               | C,C'-azodi(formamide) [123-77-3]                                        |
|                               | Melamine [108-78-1]                                                     |
| Climate                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                 |
|                               | Lead [7439-92-1]                                                        |
|                               | Melamine [108-78-1]                                                     |

|                                            |                                                                         |
|--------------------------------------------|-------------------------------------------------------------------------|
| <b>Closures and Lids BIW</b>               | Lead [7439-92-1]                                                        |
| <b>Closures and Lids Mechanisms</b>        | Boric acid [10043-35-3]                                                 |
|                                            | Lead [7439-92-1]                                                        |
|                                            | Triphenyl-phosphate [115-86-6]                                          |
| <b>Cooling</b>                             | Lead [7439-92-1]                                                        |
|                                            | TBBA [79-94-7]                                                          |
| <b>Dressed Engine</b>                      | Lead [7439-92-1]                                                        |
| <b>Driveline</b>                           | Triphenyl-phosphate [115-86-6]                                          |
| <b>Driver Controls</b>                     | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                 |
|                                            | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]            |
|                                            | Lead [7439-92-1]                                                        |
| <b>EDS</b>                                 | Lead [7439-92-1]                                                        |
|                                            | Octamethylcyclotetrasiloxane [556-67-2]                                 |
|                                            | Triphenyl-phosphate [115-86-6]                                          |
| <b>Exhaust Cold End</b>                    | Lead [7439-92-1]                                                        |
| <b>Exterior Lighting</b>                   | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
|                                            | Lead [7439-92-1]                                                        |
| <b>Fixed Glazing</b>                       | Lead [7439-92-1]                                                        |
| <b>Front / Rear Door Trim</b>              | C,C'-azodi(formamide) [123-77-3]                                        |
| <b>Fuel</b>                                | Bumetrizole [3896-11-5]                                                 |
|                                            | Imidazolidine-2-thione [96-45-7]                                        |
|                                            | Lead [7439-92-1]                                                        |
| <b>Glass Runs and Belts</b>                | Lead [7439-92-1]                                                        |
| <b>GOR and Radiator Support</b>            | Lead [7439-92-1]                                                        |
| <b>Headliner / Sunvisor</b>                | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
| <b>Interior Trim</b>                       | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
|                                            | C,C'-azodi(formamide) [123-77-3]                                        |
|                                            | Lead [7439-92-1]                                                        |
| <b>IP and Console</b>                      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                 |
|                                            | C,C'-azodi(formamide) [123-77-3]                                        |
| <b>Manual Transmission Shifter</b>         | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
| <b>Mirrors</b>                             | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
|                                            | Lead [7439-92-1]                                                        |
| <b>Multimedia</b>                          | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
|                                            | Imidazolidine-2-thione [96-45-7]                                        |
|                                            | Lead [7439-92-1]                                                        |
|                                            | N,N-Dimethylacetamide [127-19-5]                                        |
|                                            | TBBA [79-94-7]                                                          |
| <b>Overhead Console</b>                    | Lead [7439-92-1]                                                        |
| <b>Power Supply</b>                        | Lead [7439-92-1]                                                        |
| <b>Powertrain Controls and Calibration</b> | Lead [7439-92-1]                                                        |
| <b>Powertrain Mounts</b>                   | Lead [7439-92-1]                                                        |
| <b>Restraint</b>                           | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
|                                            | Lead [7439-92-1]                                                        |

|                                         |                                                                         |
|-----------------------------------------|-------------------------------------------------------------------------|
| <b>Roof</b>                             | Lead [7439-92-1]                                                        |
| <b>Seat Belts (Front and Rear)</b>      | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                 |
|                                         | Lead [7439-92-1]                                                        |
|                                         | Triphenyl-phosphate [115-86-6]                                          |
| <b>Seating</b>                          | C,C'-azodi(formamide) [123-77-3]                                        |
|                                         | Lead [7439-92-1]                                                        |
|                                         | Sodium borate, decahydrate [1303-96-4]                                  |
|                                         | TBBA [79-94-7]                                                          |
| <b>Seats - Foam - Cut and Sew</b>       | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
|                                         | Lead [7439-92-1]                                                        |
|                                         | Triphenyl-phosphate [115-86-6]                                          |
| <b>Seats - JIT</b>                      | Imidazolidine-2-thione [96-45-7]                                        |
| <b>Seats - Structures</b>               | Lead [7439-92-1]                                                        |
|                                         | N,N-Dimethylacetamide [127-19-5]                                        |
|                                         | Triphenyl-phosphate [115-86-6]                                          |
| <b>Side Door Mechanisms</b>             | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                 |
|                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
|                                         | Lead [7439-92-1]                                                        |
|                                         | O,O,O-Triphenyl phosphorothioate [597-82-0]                             |
|                                         | TBBA [79-94-7]                                                          |
| <b>Static Sealing</b>                   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                 |
| <b>Steering</b>                         | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]                 |
|                                         | Lead [7439-92-1]                                                        |
| <b>Suspension Frames and Mountings</b>  | Lead [7439-92-1]                                                        |
| <b>Switches</b>                         | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
|                                         | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]   |
|                                         | 4,4'-Isopropylidenediphenol [80-05-7]                                   |
|                                         | Lead [7439-92-1]                                                        |
| <b>Wash-Wipe</b>                        | 4,4'-Oxydianiline [101-80-4]                                            |
|                                         | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                      |
|                                         | Imidazolidine-2-thione [96-45-7]                                        |
|                                         | Lead [7439-92-1]                                                        |
|                                         | O,O,O-Triphenyl phosphorothioate [597-82-0]                             |
| <b>Wheels Tires Jacks and Equipment</b> | Lead [7439-92-1]                                                        |